





**PORSCHE**

Please note that Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If your authorized Porsche dealer is unable to perform this procedure within a reasonable period of time, you may call or write:

Porsche Cars North America, Inc.  
Attention: Customer Commitment  
980 Hammond Drive, Suite 1000  
Atlanta, GA 30328  
Telephone: 1(800) PORSCHE (1-800-767-7243)

At your option, you may notify the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We would like to take this opportunity to apologize for any inconvenience that this unscheduled repair may cause. Should you have any questions or concerns at all regarding this or any other matter, please do not hesitate to contact us.

Sincerely yours,  
PORSCHE CARS NORTH AMERICA, INC.

A handwritten signature in black ink, appearing to read "Tim Quinn".

Tim Quinn  
Vice President, After Sales



**PORSCHE**

**PORSCHE 2010 GT3**

**ADDITIONAL MAINTENANCE AND SERVICE INTERVALS  
FOR RACE TRACK USE**

The specifications for race track use as described in the 2010 GT3/GT3 RS Owner's Manual Supplement of June 2011 are now further amended by the addition of a vehicle maintenance and service interval schedule, below, as part of Porsche Recall AC05. You may also ask your authorized Porsche dealer about the current specifications **before driving your vehicle on the race track.**

Effective immediately, Porsche stipulates the following maintenance and service intervals for race track use when Porsche Genuine Parts are used:

- At the latest, every 7,000 km/4,200 miles for race track use (cumulative)
  - Replace wheel hubs and wheel bearings on rear axle
  - Replace central lock bolts on rear axle
- At the latest, every 14,000 km/8,400 miles for race track use (cumulative)
  - Replace wheel bearing housing on rear axle
  - Replace wheel hubs and wheel bearings on front axle
  - Replace central lock bolts on front axle
- At the latest, every 28,000 km/16,800 miles for race track use (cumulative)
  - Replace wheel bearing housing on front axle

As described in the 2010 GT3/GT3 RS Owner's Manual Supplement, all components of the central wheel lock, including adjacent peripheral components, must always be checked for wear and replaced if necessary **after every race track use.**

Porsche strongly recommends that all repair, service and maintenance work on your 2010 Porsche GT3 be completed at an authorized Porsche dealership who has all the necessary parts and tools to make the repairs, as well as the trained technical personnel required to keep your Porsche in top condition.